

HISTORIC AMERICAN ENGINEERING RECORD  
INDEX TO PHOTOGRAPHS

HAER  
CAL  
14-BISH.V,  
5F-

**Bishop Creek Hydroelectric System, Plant 4**  
**Worker Cottage (Building 115)**  
**Bishop Creek**  
**Bishop Vicinity**  
**Inyo County**  
**California**

**HAER No. CA-145-4-F**

Gregory L. O'Loughlin, photographer

April, 1997

- CA-145-4-F-1      EXTERIOR OVER VIEW OF PLANT 4 RESIDENTIAL COMPLEX  
SHOWING BUILDING 115 AT LEFT PHOTO CENTER (HOUSE  
WITH PROJECTING GABLE END OVERLOOKING PLANT 5  
FOREBAY. VIEW TO WEST.
- CA-145-4-F-2      EXTERIOR NORTH CORNER OF BUILDING 115. FRONT OF  
HOUSE IS SIDE AT PHOTO RIGHT WITH LARGE ARCHED  
WINDOW. WALKWAY FROM MAIN RESIDENTIAL STREET TO  
FRONT PORCH IS VISIBLE AT PHOTO RIGHT IN FRONT OF  
LARGE TREE. VIEW TO SOUTH.
- CA-145-4-F-3      EXTERIOR OF WEST CORNER OF HOUSE SHOWING BACK DOOR  
INTO UTILITY ROOM ON SOUTHWEST SIDE, CONCRETE  
WALKWAY FROM SOUTHWEST SIDE OF HOUSE, AND  
COBBLESTONE WALL AROUND FRONT PORCH. VIEW TO EAST.
- CA-145-4-F-4      EXTERIOR OF SOUTH CORNER OF HOUSE SHOWING 1-LIGHT  
OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED BEDROOM  
WINDOWS AT BACK OF HOUSE. VIEW TO NORTH.
- CA-145-4-F-5      EXTERIOR OF EAST CORNER OF HOUSE SHOWING 1-LIGHT  
OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOWS TO  
BEDROOM NO. 3 AT PHOTO CENTER. VIEW TO WEST.
- CA-145-4-F-6      EXTERIOR OF FRONT (NORTHWEST) SIDE OF HOUSE SHOWING  
EXPOSED PURLIN AND RAFTER-TAIL DETAILING, ALUMINUM-  
FRAMED SLIDING-GLASS DOOR REPLACEMENT FOR ORIGINAL  
THREE 8-LIGHT FULL-LENGTH WINDOWS, AND DUAL  
CASEMENT WINDOW TO KITCHEN AT PHOTO RIGHT MISSING  
ORIGINAL SHUTTERS. VIEW TO SOUTH.

BISHOP CREEK HYDROELECTRIC SYSTEM, PLANT 4,  
WORKER COTTAGE (BUILDING 115  
HAER No. CA-145-4-F  
INDEX TO PHOTOGRAPHS (Page 2)

- CA-145-4-F-7      EXTERIOR DETAIL OF FRONT OF HOUSE SHOWING ARCHED, 3-PART SEGMENTAL WINDOW, CONCRETE WALK AND STEPS TO FRONT PORCH, AND OPEN FRONT DOOR. VIEW TO SOUTHEAST.
- CA-145-4-F-8      EXTERIOR DETAIL SHOWING CONCRETE-LAID ANGULAR-STONE RETAINING WALL ABOVE FRONT WALKWAY, AND CONCETE-LAID COBBLESTONE WALL AROUND FRONT PORCH. VIEW TO SOUTHWEST.
- CA-145-4-F-9      INTERIOR OF LIVING ROOM SHOWING TAPERED CEILING, AND ARCHED, 3-PART SEGMENTAL WINDOW FLANKED AT PHOTO LEFT BY THE FRONT DOOR AND AT PHOTO RIGHT BY FULL-LENGTH, PAIRED 8-LIGHT CASEMENT WINDOWS. VIEW TO NORTHWEST.
- CA-145-4-F-10     INTERIOR OF LIVING ROOM FROM DINING ROOM SHOWING ORIGINAL FIREPLACE WITH RECENT BRICK FACADE FLANKED BY FULL-LENGTH, PAIRED 8-LIGHT CASEMENT WINDOWS. VIEW TO NORTHEAST.
- CA-145-4-F-11     INTERIOR OF DINING ROOM FROM LIVING ROOM SHOWING OPEN PANEL DOOR TO KITCHEN IN BACKGROUND. VIEW TO SOUTHWEST.
- CA-145-4-F-12     INTERIOR OF DINING ROOM SHOWING OPEN PANEL DOOR TO KITCHEN AND CURTAINS SHIELDING SLIDING-GLASS DOOR AT PHOTO RIGHT. VIEW TO WEST.
- CA-145-4-F-13     INTERIOR OF KITCHEN SHOWING 1950s STYLE BUILT-IN CABINETS, PAIRED CASEMENT WINDOWS ON NORTHWEST WALL AT PHOTO RIGHT, AND 1-LIGHT OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOW OVER SINK AT PHOTO LEFT. VIEW TO WEST.
- CA-145-4-F-14     INTERIOR KITCHEN DETAIL SHOWING RECESSED TELEPHONE ALCOVE. VIEW TO EAST.
- CA-145-4-F-15     INTERIOR OF KITCHEN SHOWING OPEN DOORWAY INTO UTILITY ROOM AND RECESSED AREA IN SOUTHEAST WALL WITH REFRIGERATOR. VIEW TO SOUTHEAST.

BISHOP CREEK HYDROELECTRIC SYSTEM, PLANT 4,  
WORKER COTTAGE (BUILDING 115  
HAER No. CA-145-4-F  
INDEX TO PHOTOGRAPHS (Page 3)

- CA-I45-4-F-16 INTERIOR OF UTILITY ROOM SHOWING PAIRED CASMENT WINDOWS AND PANELED AND GLAZED REAR DOOR. VIEW TO SOUTH.
- CA-145-4-F-17 INTERIOR OF MAIN HALL SHOWING DOORWAY FROM DINING ROOM. SIDE HALL ENTERS MAIN HALL FROM LEFT AT PHOTO CENTER UNDER CEILING LIGHT. VIEW TO WEST.
- CA-I45-4-F-18 INTERIOR OF MAIN HALL SHOWING 1-LIGHT OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOW AT SOUTHEAST END. DOORWAY TO BEDROOM NO. 2 IS OPEN AT PHOTO LEFT. BEDROOM NO. 3 IS ACCESSED TO THE LEFT AT END OF HALL NEXT TO THE WINDOW. VIEW TO EAST.
- CA-145-4-F-19 INTERIOR OF SIDE HALL SHOWING DOORWAY TO BATHROOM AT PHOTO LEFT. DOORWAY AT END OF SIDE HALL (PHOTO RIGHT) LEADS TO BEDROOM NO. 1. VIEW TO SOUTH.
- CA-I45-4-F-20 INTERIOR OF SIDE HALL SHOWING LINEN CLOSET AT PHOTO RIGHT. OPEN PANELED DOOR AT PHOTO CENTER NEXT TO LINEN CLOSET LEADS TO ATTIC STAIRWAY. DOORWAY ADJACENT TO ATTIC STAIRWAY DOOR AT PHOTO LEFT LEADS TO BEDROOM NO. 1. VIEW TO WEST.
- CA-I45-4-F-21 INTERIOR OF BATHROOM SHOWING NARROW CASEMENT WINDOW ABOVE BUILT-IN VANITY WITH DRAWERS. VIEW TO SOUTH.
- CA-145-4-F-22 INTERIOR OF BEDROOM NO. 1 SHOWING DOORWAY TO CLOSET AT PHOTO RIGHT CENTER, AND OPEN PANELED ENTRY DOOR AT PHOTO RIGHT. VIEW TO WEST.
- CA-145-4-F-23 INTERIOR OF BEDROOM NO. 1 SHOWING 1-LIGHT OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOWS ON SOUTHEAST AND SOUTHWEST WALLS. VIEW TO SOUTH.
- CA-145-4-F-24 INTERIOR OF BEDROOM NO. 2 SHOWING SIDE HALL TO BEDROOM NO. 1 (BACKGROUND) THROUGH OPEN DOOR. VIEW TO SOUTHWEST.
- CA-145-4-F-25 INTERIOR OF BEDROOM NO. 2 SHOWING OPEN PANELED DOOR LEADING TO THE WALK-IN CLOSET, 1-LIGHT OVER 1-LIGHT,

BISHOP CREEK HYDROELECTRIC SYSTEM, PLANT 4,  
WORKER COTTAGE (BUILDING 115  
HAER No. CA-145-4-F  
INDEX TO PHOTOGRAPHS (Page 4)

DOUBLE-HUNG, WOOD-FRAMED WINDOWS ON NORTHEAST WALL, AND A SINGLE, SMALL CASEMENT WINDOW ON THE SAME WALL INSIDE THE CLOSET. VIEW TO NORTHEAST.

CA-145-4-F-26 INTERIOR OF BEDROOM NO. 3 SHOWING OPEN WALK-IN CLOSET, AND ONE OF A PAIR OF 1-LIGHT OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOWS ARRANGED SINGLY ON THE NORTHEAST WALL. VIEW TO NORTH.

CA-145-4-F-27 INTERIOR OF BEDROOM NO. 3 SHOWING SINGLE 1-LIGHT OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOWS PIERCING THE SOUTHEAST AND SOUTHWEST WALLS. VIEW TO SOUTH.